ECS Configuration Change Request Page For Pages						
CCR No. 98- C	504 Logged D	ate 4/22/98	Rev Request T		ype CCR	
Priority Routine	Urgent x	Emergency	Affected Release		Change Class	IN\$
Title (description) contact the contact of the cont						
Documents Affected	d		Source Nos (RID, NCR, Action Item, GSFC CCR, etc.) or Tech Reference			
VCATS						
RTM Change  Start New Baseline						
Problem ECS Custom code requ code readers.	ires the use of bar code	readers on 8mm and 4n	nm stackers. The existi	ng stackers in	the EDF do not ha	ve bar
			00000.07			
Proposed Solution 4mh 43clp godisol CCCC1875 added to Request that an existing GSFC 8mm stacker; with bar code reader (going 02, 00001116) be exchanged with an EDF non-bar code reader 8mm stacker.  reader ein 2232 (part to be transferred)  tarset platform! Lioux, ein 1029  Need Date: 4/29/98						
Impact Analysis:					_	_
Organizations Affected:  Procurement	BOO □	Contracts E	ECS Chief Eng Rel. A	FOS Rel. C	M&O [ SCDO Arch. [	
Science Off		Subcontrct	Sys. Eng	Sys Verf Acpt		_
Cost:	None x	Small [	Medium	Large (Over \$500,000)		
Schedule:	None	Other		************************		
Additional LOC			Man-Months			
Materials						
Originator Alla Lake		Signatures		<del></del>	4/22/.	38
Office	Office Manager	Signature		)	4/27/ Date	198
Disposition	Approved 🔽	Approved w/Comn	nent Forw	ard	Disapproved [	
Comments:						
	CCB Chairperson	Signature	amt		4/29/9.	<u>8</u>

ORIGINAL

CM01OC96

Sm/cm